

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	:	D2365
Job Number	: 27928			
Estimate Number	: 10804			
P.O. Number	: N/A	Part Number	:	D2365
This Issue	: 17/07/2006 S.O. No. : N/A	Drawing Number	:	FINISH PER DRWG
Prsht Rev.	: NC	Project Number	:	N/A
First Issue	: 17/07/2006 Type : N/A	Drawing Revision	:	N/A
Previous Run	: 00015	Material	:	N/A
Written By	: <u>SEE ABOVE USER & DATE</u>	Due Date	:	24/07/2006
Checked & Approved By	: _____	Qty:		21
Comment	:	Um:		Each

Additional Product

Job Number: 

Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
-----	-------------	-------------------------------

Journal of Management Education 30(6)br/>© The Author(s)
10.1177/0095647206288111
<http://jme.sagepub.com>

[illegible]

Comment: SMALL & MEDIUM FAB RESOURCE 1
REMOVE FROM STK
D2365 B 23759

SB 06/07/17 21

2.0	D2365	Wear Plate
-----	-------	------------

[illegible]

1000

Comment: Qty.: 1.0000 Each(s)/Unit Total: 21.0000 Each(s)
Wear Plate

SB 06/07/17 (21)

3.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
-----	-------------	-------------------------------

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the project.

3. The third step is to develop a plan or strategy to address the problem. This involves identifying the resources needed, the timeline, and the specific actions to be taken.

4. After the plan is developed, the next step is to implement the plan. This involves putting the plan into action and monitoring progress.

5. The final step is to evaluate the results of the project. This involves assessing whether the objectives were met and identifying any lessons learned for future projects.

[illegible]

Comment: SMALL & MEDIUM FAB RESOURCE 1
INSTALL INSERT PER DRWG D2365 REV.C
FE832EF B M 101483

m.f. 06/07/17 (21)

4.0 FE832EF PEM Insert

...the ... of ...

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

Comment: Qty.: 2.0000 Each(s)/Unit Total: 42.0000 Each(s)
PEM Insert M 101483

SPB 06/07/17/21

5.0 QC5 INSPECT WORK TO CURRENT STEP

[illegible]

Comment: INSPECT WORK TO CURRENT STEP

SB 06/07/17 (29)

Date: Monday, 17/07/2006 9:55:47 AM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D2365

Job Number: 27928

Part Number: D2365

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1
IDENTIFY & STK USING NEW B/N

STYU PU 6/7/17 (21)

7.0

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL
INSPECT LEVEL 21

1A 06.07.18












Job Completion




U 06.07.17

Date: Monday, 17/07/2006 8:13:59 AM
User: Linda Lacelle

Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd..	Drawing Name : D2365
Job Number : 27928	
Estimate Number : 10804	
P.O. Number :	Part Number : D2365
This Issue : 17/07/2006 S.O. No. :	Drawing Number : FINISH PER DRWG
Prsht Rev. : NC	Project Number :
First Issue : / / Type :	Drawing Revision :
Previous Run : 00015	Material :
Written By :	Due Date : 24/07/2006 Qty: 21 Um: Each
Checked & Approved By :	
Comment :	
Additional Product	
Job Number: 	
Seq. #:	Machine Or Operation:
Description :	
1.0 SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
	
Comment: SMALL & MEDIUM FAB RESOURCE 1 REMOVE FROM STK D2365 B _____	
2.0 D2365	Wear Plate
	
Comment: Qty.: 1.0000 Each(s)/Unit Total : 21.0000 Each(s) Wear Plate	
3.0 SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
	
Comment: SMALL & MEDIUM FAB RESOURCE 1 INSTALL INSERT PER DRWG D2365 REV.C FE832EF B <u>M 101 483</u>	
4.0 FE832EF	PEM Insert
	
Comment: Qty.: 2.0000 Each(s)/Unit Total : 42.0000 Each(s) PEM Insert	
5.0 QC5	INSPECT WORK TO CURRENT STEP
	
Comment: INSPECT WORK TO CURRENT STEP	



Date: Monday, 17/07/2006 8:13:59 AM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D2365

Job Number: 27928

Part Number: D2365

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1
IDENTIFY & STK USING NEW B/N

7.0

DC

DOCUMENT CONTROL




Comment: DOCUMENT CONTROL
INSPECT LEVEL 21

Job Completion



DART

DESIGN	DRAWN BY	DART AEROSPACE LTD	
B WILLIAMS	B WILLIAMS	VICTORIA	INTERNATIONAL AIRPORT, CANADA
CHECKED	APPROVED	DRAWING NO.	REV. C
BW	[Signature]	D2365	SHEET 1 OF 1
DATE	TITLE		SCALE
95:01:20	WEAR PLATE		2:1
C	95:03:06	0.191 WAS 0.197	

RELEASED
97/04/22 DS

6061-T6 (00-A-250/11) 0.063 THICK } # 00.09.26
ACID ETCH & ALODINE PER QSI 005 4.1.1 } #
AKI 304/316 SS INSTAL FE832EF (2 PLS) AFTER ALODINE } # 00.03.07

MATERIAL: 6061-T6 ALUMINUM 0.063 THICK, ANODIZE BLACK.
AFTER ANODIZING INSTALL (PEM FE832EF) 2 PLACES } #